Solvent wash down area- UK

- Global car parts manufacturer awarded a further contract to Mark Specialist Coatings to seal the leaking joints on a wash down tunnel
- The tunnel was constructed and the solvent wash was leaking into other areas of the factory



Surface Prep

- All surfaces were mechanically abraded using MBX Bristle Blasters

Application

- To seal the joints 301 Epoxy Resin and Hardener was coated on to the joint
- While still wet glass tape was incorporated into resin
- Once cured 1 x coat of Resichem 507 DWPU was applied at 1mm wet film thickness

Project Completion

- Resichem 507 DWPU is a 100% solids PU coating which gives outstanding flexibility once cured.

resimac Ltd.