




EU Refinery

- Oil storage tank was badly corroded and required coating with UV stable coating
- Surface preparation was restricted due to the tanks location



Surface Prep

- All surfaces were hydro-blasted at 30,000 psi



Application

- All edges and equipment were stripe coated using Resichem 555 Resinox
- Once cured 2 x coats of Resichem 555 Resinox were applied by spray at a nominal WFT of 500 microns



Project Completion

- The tank refurbishment contract was completed over 5 days
- Due to the performance of 55 Resinox a contract was awarded to the applicator to refurbish 5 x 75mtr dia storage tanks